

ELGIN

SEARS ROEBUCK & COMPANY
925 S. Homan Ave., Chicago, Ill.

Elgin outboard motors are manufactured for Sears Roebuck & Co. by The West Bend Company, Hartford, Wisc.; or by McCulloch Corporation, Los Angeles 45, Calif.

Service procedures on these units will not differ greatly from those given for similar motors carrying the manufacturer's brand name. This does not necessarily mean, however, that parts are interchangeable. If parts are required, refer to the PARTS PROCUREMENT INFORMATION data following the model listing.

Elgin Model	Refer to following:			Elgin Model	Refer to following:		
	Year	Manufacturer	Section		Year	Manufacturer	Section
571.58211	1955	West Bend	2 hp	574.60801	1959	Scott	60 hp
571.58571	1955	West Bend	5 hp	574.60611	1959	Scott	60 hp
571.58771	1955	West Bend	7.5 hp	571.58321	1960	West Bend	2 hp
571.58772	1955	West Bend	7.5 hp	574.60000	1960	Scott	3.6 hp
571.58901	1955	West Bend	12 hp	574.60070	1960	Scott	7.5 hp
571.59401	1955	West Bend	25 hp	574.60120	1960	Scott	12 hp
571.58221	1956	West Bend	2 hp	574.60290	1960	Scott	25 hp
571.59501	1956	West Bend	5½ hp	574.60300	1960	Scott	25 hp
571.58772	1956	West Bend	7½ hp	574.60310	1960	Scott	25 hp
571.58902	1956	West Bend	12 hp	574.60320	1960	Scott	25 hp
571.59402	1956	West Bend	25 hp	574.60440	1960	Scott	40 hp
571.58221	1957	West Bend	2 hp	574.60450	1960	Scott	40 hp
571.58781	1957	West Bend	7½ hp	574.60460	1960	Scott	40 hp
571.59521	1957	West Bend	6 hp	574.60470	1960	Scott	40 hp
571.59721	1957	West Bend	8 hp	574.60230	1960	Scott	60 hp
571.58941	1957	West Bend	12 hp	574.60630	1960	Scott	60 hp
571.58951	1957	West Bend	12 hp	571.58322	1961	West Bend	2 hp
571.59421	1957	West Bend	30 hp	574.60010	1961	Scott	3.6 hp
571.59431	1957	West Bend	30 hp	574.60050	1961	Scott	6 hp
571.59621	1957	West Bend	30 hp	574.60080	1961	Scott	7.6 hp
571.59631	1957	West Bend	30 hp	574.60130	1961	Scott	14 hp
571.59801	1957	West Bend	30 hp	574.60330	1961	Scott	27 hp
571.59811	1957	West Bend	30 hp	574.60350	1961	Scott	27 hp
571.58231	1958	West Bend	2 hp	574.60440	1961	Scott	43 hp
571.59531	1958	West Bend	6 hp	574.60450	1961	Scott	43 hp
571.59732	1958	West Bend	8 hp	574.60500	1961	Scott	43 hp
571.58782	1958	West Bend	7½ hp	574.60510	1961	Scott	43 hp
571.58931	1958	West Bend	12 hp	574.60700	1961	Scott	75 hp
571.58961	1958	West Bend	12 hp	574.60710	1961	Scott	75 hp
571.58971	1958	West Bend	12 hp	5833	1962	West Bend	2 hp
571.59441	1958	West Bend	35 hp	6001	1962	Scott	3.6 hp
571.59451	1958	West Bend	35 hp	6005	1962	Scott	6 hp
571.59821	1958	West Bend	35 hp	6008	1962	Scott	7.5 hp
571.59831	1958	West Bend	35 hp	6013	1962	Scott	14.1 hp
571.59901	1958	West Bend	35 hp	6033	1962	Scott	27.7 hp
571.59911	1958	West Bend	35 hp	6035	1962	Scott	27.7 hp
571.58241	1959	West Bend	2 hp	6052	1962	Scott	43.7 hp
571.59541	1959	West Bend	6 hp	6053	1962	Scott	43.7 hp
571.59741	1959	West Bend	8 hp	6072	1962	Scott	75.2 hp
571.58791	1959	West Bend	7½ hp	6073	1962	Scott	75.2 hp
571.58981	1959	West Bend	12 hp	5825	1963	West Bend	2 hp
571.58991	1959	West Bend	12 hp	6002	1963	Scott	3.6 hp
571.58801	1959	West Bend	12 hp	6005	1963	Scott	6 hp
574.60251	1959	Scott	25 hp	6009	1963	Scott	7.5 hp
574.60261	1959	Scott	25 hp	6014	1963	Scott	14.1 hp
574.60271	1959	Scott	25 hp	6034	1963	Scott	28 hp
574.60281	1959	Scott	25 hp	6036	1963	Scott	28 hp
574.60401	1959	Scott	40 hp	6054	1963	Scott	45 hp
574.60411	1959	Scott	40 hp	6055	1963	Scott	45 hp
574.60421	1959	Scott	40 hp	6074	1963	Scott	75.2 hp
574.60431	1959	Scott	40 hp	6075	1963	Scott	75.2 hp

PARTS PROCUREMENT

Parts for Elgin motors are supplied by Sears Roebuck & Co., and a parts inventory is maintained at 37 locations across the country. When parts are required, contact the nearest SEARS ROEBUCK Catalog Sales Office or Retail Store; or write direct to the applicable Mail Order Store, giving model number and serial number of motor.